


Technical bulletin




We would like to inform you that if you need to replace the battery charger of the radio kit on the above-mentioned machines manufactured before 2016, the code required is 4-328832. Serial numbers of machines up to CLNxxxxxx.

On machines manufactured from 2016 to the present day (serial no. CMAxxxxxx onwards), the code of the battery charger to be ordered is 4-330050D.

This note is required due to a change in the electronic board created in 2016. Match the correct battery charger based on the new resistors installed.

This change can be quickly recognised as follows:



Board before 2016: requires battery charger with code **4-328832**



Board from 2016: requires battery charger with code **4-330050D**

Date:

23.04.2021

Product:

HD1200 - HD1200E

HD1400 - HD1400E

HD1000R - HD1000AR

Subject:

Battery charger for radio kit

Technical bulletin:

148

Page:

1/1